



# Technical Note

## MT9T012 Revision 1 Features

### Introduction

This technical note addresses the Micron<sup>®</sup> MT9T012 Revision 1 CMOS image sensor, which adds an additional processing step to the digital data path in order to provide color-dependent lens correction (position-dependent digital gain control). This revision has a number of additional functional changes to improve the operation of the sensor.

### Identification

The MT9T012 Revision 1 is distinguished from earlier revisions by the value of its revision\_number register (Reg0x0002). For Revision 1, this register has the value “1.”

### Additional Registers

Table 1 shows the register list and default value for new registers in this revision.

**Table 1: New Register List and Default Value**

1 = read-only, always 1; 0 = read-only, always 0; d = programmable; ? = read-only, dynamic

Register Name	Address (Hex)	Data Format (Binary)	Default Value (Hex)
lens_correction	0x318A–0x318B	d000 0000 0000 0000	0x0000
	0x3600–0x3601	TBD	UNDEFINED
	0x3696–0x3697	—	UNDEFINED

### Changes To Default Register Values

Table 2 shows registers whose default values have changed for this revision. The change to the default value of revision\_number distinguishes Revision 1 from earlier revisions. The change to the default value of digital\_gain\_max corrects an error in the declaration of the maximum supported digital gain; it does not reflect a change to the digital gain capability of the sensor. The other default changes are intended to optimize imaging performance under some conditions.

**Table 2: Register List showing Changes to Default Value**

1 = read-only, always 1; 0 = read-only, always 0; d = programmable; ? = read-only, dynamic

Register Name	Address (Hex)	Data Format (Binary)	Default Value (Hex)
revision_number	0x0002	0000 0000	0x01
digital_gain_max	0x1086–0x1087	0000 0111 0000 0000	0x0700
Reserved	0x308C–0x308D	—	0x0507
Reserved	0x309E–0x309F	—	0x1410
Reserved	0x30E8–0x30E9	—	0xEFC1


**Table 2: Register List showing Changes to Default Value (continued)**

1 = read-only, always 1; 0 = read-only, always 0; d = programmable; ? = read-only, dynamic

Register Name	Address (Hex)	Data Format (Binary)	Default Value (Hex)
Reserved	0x30F0–0x30F1	—	0x764D
Reserved	0x30F6–0x30F7	—	0xF01A
Reserved	0x30FE–0x30FF	—	0x9176
Reserved	0x3100–0x3101	—	0x9176
Reserved	0x3102–0x3103	—	0xBF9B
Reserved	0x3104–0x3105	—	0xEEC2

## Lens Correction

The lens correction function is disabled by default. It is enabled by setting `lens_correction[15] = 1` and disabled by setting `lens_correction[15] = 0`. The lens correction configuration registers (Reg0x3600-3697) are UNDEFINED after reset. They must be initialized before enabling the lens correction function. The lens correction configuration registers should only be written while the lens correction function is disabled. The lens correction function should only be enabled and disabled while the sensor is in software standby.

The settings for the lens correction configuration registers are a function of the optical system in use.

## Additional Subsampling Mode

MT9T012 Revision 1 supports an additional subsampling value, `y_odd_inc = 7`. This provides a mechanism for reducing the amount of frame data associated with a full-frame image, which also allows the frame rate to be increased. In contrast, images of equivalent size generated by the integrated scaler will be of higher image quality (will not suffer from the same subsampling image artifacts) but do not allow the frame rate to be increased.

When subsampling is enabled, it may be necessary to adjust the `x_addr_end` and `y_addr_end` settings. The values for these registers are required to correspond with rows/columns that form part of the subsampling sequence. For an `x_odd_inc = 3`, or a `y_odd_inc = 3`, the adjustment should be made in accordance with the following rule:

$$\text{remainder} = (\text{addr\_end} - \text{addr\_start} + 1) \text{ AND } 2$$

$$\text{if } (\text{remainder} == 0) \text{ addr\_end} = \text{addr\_end} - 2$$

For a `y_odd_inc = 7`, the adjustment should be made in accordance with the following rule:

$$\text{remainder} = (\text{y\_addr\_end} - \text{y\_addr\_start} + 1) \text{ AND } 7$$

$$\text{if } (\text{remainder} == 0) \text{ y\_addr\_end} = \text{y\_addr\_end} - 6$$

$$\text{if } (\text{remainder} == 6) \text{ y\_addr\_end} = \text{y\_addr\_end} - 4$$

$$\text{if } (\text{remainder} == 4) \text{ y\_addr\_end} = \text{y\_addr\_end} - 2$$

## Correction to Embedded Data

MT9T012 Revision 1 generates the `x_odd_inc` and `y_odd_inc` values in the correct position in the embedded data. In previous revisions, the values for `x_odd_inc` and `y_odd_inc` were swapped in the embedded data.



## **Correction to ccp2\_signalling\_mode Behavior**

MT9T012 Revision 1 allows the setting of `ccp2_signalling_mode` to be changed from “1” (the default value) to “0,” and from “0” to “1.” In previous revisions, the sensor would not operate correctly if the `ccp2_signalling_mode` was changed from “0” to “1.”

## **Correction to PLL Divisors Updates**

A change to the value of `ccp2_signalling_mode` causes the PLL settings to change, in order to meet the SMIA clocking model. MT9T012 Revision 1 changes these settings while the sensor is in software standby. In previous revisions, the settings were not changed until the sensor entered streaming mode; this could result in the PLL losing lock, resulting in an undetected bad frame being generated from the sensor.

## **Correction to Behavior when Horizontal Mirror is Enabled/Disabled**


MT9T012 Revision 1 generates a bad frame when `image_orientation[0]` is toggled (enable or disable horizontal mirror). When `mask_corrupted_frames = 1`, this bad frame is masked within the sensor. In previous revisions, the bad frame was generated at the sensor output regardless of the setting of `mask_corrupted_frames`.

## **Addition of PLL Lock Timer**

MT9T012 Revision 1 implements a PLL lock timer and powers down the PLL VCO while the sensor is in software standby. As a result, the power consumption is reduced while the sensor is in software standby. When the sensor enters streaming mode (`mode_select = 1`) streaming does not commence until the PLL has acquired lock. This change introduces a new state to the System State machine, as shown in Figure 1 on page 4. The effect of `RESET#` on the system state and the configuration of the PLL in the different states are shown in Table 3 on page 4.



**Figure 1: MT9T012 Revision 1 System States**



**Table 3: RESET# and PLL in System States**

State	RESET#	PLL
Powered off	x	VCO powered down
POR Active	x	
Hardware Standby	0	
Internal Initialization	1	VCO powered down, PLL clock outputs bypassed by EXTCLK
Software Standby		
Lock		
Streaming		
Wait for frame end		
		VCO running, PLL clock outputs active



## **PLL VCO Power-down**

In the MT9T012 Revision 1, the PLL VCO is automatically powered down when the sensor is in streaming mode. Reg0x301A-B[5] has no influence upon the operation of the PLL VCO. In previous revisions, the PLL VCO remained powered while the sensor was in streaming mode and could be manually powered down by setting Reg0x301A-B[5] = 1.

## **Correction to ADC Monotonicity**

MT9T012 Revision 1 exhibits monotonic gain changes as a result of changes in the LSB of the gain control. In previous revisions, changes in the LSB of the gain control could result in non-monotonic gain changes.

## **Conclusion**

For more information on MT9T012 Revision1 features, refer to the latest data sheet located at Micron's Web site at [www.micron.com/imaging](http://www.micron.com/imaging).



**8000 S. Federal Way, P.O. Box 6, Boise, ID 83707-0006, Tel: 208-368-3900  
prodmktg@micron.com www.micron.com Customer Comment Line: 800-932-4992  
Micron, the M logo, and the Micron logo are trademarks of Micron Technology, Inc.  
All other trademarks are the property of their respective owners.**



## Revision History

Rev A.....	3/06
• Initial release	