

MT9M002: 1/4.5-Inch 1.6Mp Digital Image Sensor ERRATA Introduction

1/4.5-Inch 1.6Mp Digital Image Sensor

MT9M002

Silicon Revision 2 Errata

Refer to the MT9M002 data sheet at www.aptina.com

Introduction

This errata summarizes known issues to date for Aptina's MT9M002 Silicon Revision 2 (Rev2). This errata is provided for customer information at this time. Any permanent changes will be incorporated into the next revision of the data sheet.

Table 1: Known Issues and Workarounds

Issue #	Title Description Workaround	Details
1	Title	Required initial settings.
	Description	Power-on default values for some registers are not optimized.
	Workaround	Host must load register values from Table 2. This issue will be addressed in revision 3.
2	Title	Unreliable operation of sensor at EXTCLK above 16.5 MHz.
	Description	The Rev2 silicon sometimes has problems with PLL initialization after RESET, its maximum EXTCLK frequency needs to be limited to 16.5 MHz.
	Workaround	Lower the EXTCLK maximum frequency to 16.5 MHz from 49.5 MHz. Refer "MT9M002: PLL Setup and Control addendum" for details.

Table 2: Required Register Settings for Optimized Performance

Register Address	Register Data	
R0x41	0x0000	
R0x42	0x0003	
R0x43	0x0003	
R0x7F	0x0000	



MT9M002: 1/4.5-Inch 1.6Mp Digital Image Sensor ERRATA Introduction

Table 3: Frequency Parameters

Symbol	Parameter	Condition	Min	Тур	Max	Unit
^f EXTCLK	Input clock frequency	PLL enabled	8	_	16.5	MHz
^f VCO	VCO Frequency	^f EXTCLK * PLL_m_factor /(PLL_n_divider + 1)	320	-	693	MHz



MT9M002: 1/4.5-Inch 1.6Mp Digital Image Sensor ERRATA Revision History

Revision History

Rev. F	
	Updated trademarks
	Applied updated template
Rev. E	5/19/10
	Updated to Aptina template
Rev. D	11/13/07
	• Added VCO frequency to Table 3, "Frequency Parameters," on page 2, changed title
Rev. C	8/20/07
	• Added issue two in Table 1, "Known Issues and Workarounds," on page 1
	 Added Table 3, "Frequency Parameters," on page 2
Rev. B	5/23/07
	• Updated Table 2, "Required Register Settings for Optimized Performance," on page 1
Rev. A	
	Initial release

10 Eunos Road 8 13-40, Singapore Post Center, Singapore 408600 prodmktg@aptina.com www.aptina.com Aptina, Aptina Imaging, and the Aptina logo are the property of Aptina Imaging Corporation All other trademarks are the property of their respective owners.

Advance: This data sheet contains initial descriptions of products still under development.